


CONTROL AN ANTARI IP-1000 FOG MACHINE FROM A PICOBOO

The Antari IP-1000 fog machine does not have a timer accessory. This shows you how to use a PicoBoo to act as a timer.



To set the fog burst and delay times:

- Tap the red REC button
- Hold button "1" in to produce fog, let go when done
- Wait for up to 2 minutes (delay time)
- Tap REC button to save

You can now put a jumper wire into "-" and "IN" on the trigger terminals to have it repeat the sequence endlessly.